

BY  
dealt with.  
EYORS

BW 7023  
338 F

# Lloyd's Register of Shipping.

4 BRIDGE STREET.

SYDNEY, 12th June 1933.

N.S.W.



The Secretary,

Sir,

In reply to your classing letter of the 28th April 1933 regarding the steamer "CHRISTINA FRASER", Sydney N.S.W. Report No.13007, beg to state that the No.3 double bottom tank (under boiler) is marked "Dry Tank" on shipbuilders plan on board the vessel.


The suction pipe from this tank is connected to a ballast tank distribution chest, the valve for this tank being non-return, and marked "Dry Tank".

No alterations appear to have been made to these pumping arrangements.

I am, Sir,

Your obedient Servant,

*J. C. Bushni*



© 2020

Lloyd's Register  
Foundation

W580-0193

Expenses (if chargeable) ..... £  
Overtime fee

21 2 0

Received by me,

19

Surveyor to Lloyd's

161

tee.

filled

stuntity

17/33

Referred to Mr. Dyers

02

Referred to Mr. Spinks.

WJB

17 JUL 1937

[Handwritten signature]

W. H. H. /



© 2020

Lloyd's Register  
Foundation

NAME of  
the Ship

of the

las

The lot

further a

the foll

the

It is pr  
It is su  
ved to r

S.S. I

OK

The fol

Committee