





Grounding damage  
Jacking Screw shaft end  
S.S. no 2 due P. 29 now tilted  
on rollers

It is suggested that  
this vessel is eligible for  
THE RECORD.

+L/MC MS 5.30

P. 5.30

Rm  
5.6.30

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register  
Foundation