

COPY.

# Lloyd's Register of Shipping.



Port of BREMEN.

Augsburg, 24th February 1934

781070/80  
G6Vu74  
1627.

This is to Certify that

Victor Sdrowok

the undersigned Surveyor to this Society did at the request of Messrs. Maschinenfabrik Augsburg-Nürnberg A.G. attend at their works at Augsburg on various dates for the purpose of surveying during construction one starting air receiver of 1100 ltr. capacity to the order of Messrs. Wm. Simons & Co. of Rehfrew and destined for their yard No. 704.

This starting air receiver has been surveyed during construction by the undersigned. The material has been tested by the Society's Surveyors and the scantlings are in accordance to the approved plan M 17807 and instructions thereto.

The starting air receiver has been riveted and the workmanship thereon is satisfactory.

The starting air receiver has been submitted to internal hydraulic pressure of 45 atm. in my presence, showed no signs of weakness and was found tight and sound in every respect at this pressure. Working pressure not to exceed 30 atm.

For identification purposes the starting air receiver has been stamped:-

Lloyds test  
V.S. 1627  
45 atm.  
W.P. 30 atm.  
V.S. 23.2.34.



*L. Sdrowok*  
Surveyor to Lloyd's Register.

For results of test to the material see Certificates:-  
Shell plates and end plates, Cert. 6471. Düsseldorf; Compensating ring, Cert. 1627 Augsburg Office, Valve head, Certificate 1627, Augsburg Office; Rivet bars, Cert. 6469/47736 Düsseldorf Office.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or Surveyors, or other Officers or Agents of the Society."

© 2019  
Lloyd's Register  
Foundation  
W6-0140