

The Class is subject to the Donkey Boiler not being used.

4E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME

s.s. "MOUNT ATHOS"

Rpt.

Rot.

No. 25836

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

The Rotterdam Surveyors now report that a second-hand Donkey Boiler has been fitted. The scantlings of this boiler are in accordance with the Rules for a working pressure of 90 lb./sq.in. and found in good order.

Some condenser tubes and ferrules renewed and feed water heater fitted.

Docking.

It is submitted the vessel appears worthy to remain as Classed without fresh record of survey and without special condition.

N. D.B. '06 refitted '37.
D.B. pressure 90 lb.

10. 8. 37.



© 2020

Lloyd's Register
Foundation

W60-0086

fresh record of D.B.' 7-37