

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

12 JUN 1930

Date of writing Report June 11 1930 when handed in at Local Office June 11 1930 Port of Falmouth

No. in Reg. Book 26155 Survey held at Falmouth Date, First Survey 7 Last Survey June 5 1930

on the Machinery of the ~~Wood~~ Steel SS "LA CRESCENTA"

Tonnage Gross 5210 Net 3531 Vessel built at Haverton Hill By whom Furness S B Co Ltd. When 1923-6

Nominal Horse Power 575 Engines made at Middlesbrough By whom Wm Westgarth & Co Ltd When 1923

No. of Main Boilers 3 Boilers, when made (Main) 1923 (Donkey)

No. of Donkey Boilers 1 Owners Crescent Navigation Co Ltd Managers' Address Harris & Dixon Ltd Port London Voyage Voyage

Steam Pressure in Main Boilers 180 If Surveyed Afloat or in Dry Dock Fal No 2 Dock

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Examination and Repairs (if any) Docking

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. Donkey

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boiler?

Has screw shaft now been drawn and examined? no Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

state the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft to base

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Vessel in dry docks. propeller & sea fastenings examined

General Observations, Opinion, and Recommendation:— The machinery of this vessel is eligible in my opinion to remain as classed

Survey Fee (per Section 29)	£	:	Fees applied for
Special Damage or Repair Fee (if any) (per Section 29.)	£	:	19
Travelling expenses (if chargeable)	£	:	Received by me,
			19

Committee's Minute  
Assigned

© 2019  
R. M. Pitt  
Engineer Surveyor to Lloyd's Register of Shipping  
Lloyd's Register Foundation  
W604-0024

4. Survey as seen had: on Ship  
 if so, is the Report sent now, or when will it be sent?  
 13m. 100 - Transfer Ink  
 (The Surveyors are requested not to write on or below the lines for Committee's Minute.)  
 This is a certificate required: if so to be sent to