


S.S. "LA CRESCENTA".

It is submitted the Falmouth Surveyors be reminded that the original welding repair to plate E4 port was carried out at their port in September 1928 (Falmouth Report No.6861). They should therefore state if there is any entry in their Journal, of if they can recall any information, as to the size of the original fracture found, and whether it had increased in size prior to the re-welding in June 1930.

They should also be reminded that the re-welding which was carried out in June 1930 and which they state "appears to "have been most efficient" was again found defective, and the fracture was re-welded at Barry, three months later.

*Pl. 2/8/35
Recd. 6/8/35.*



6. 8. 35.



© 2019

Lloyd's Register
Foundation

W604-0297