

W605-0159

833.

1- SEP 1934

ved by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME Sc.K. "MACLEAY" Rpt. Gms No. 19028

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey


The class is subject to the stem being dealt with at the Owners' convenience.

The Grimsby Surveyors now report this trawler placed in dry dock, bottom cleaned and coated, a shell plate renewed and minor repairs effected.

On account of damage (as above) through striking quay wall, 6 shell plates have been renewed, 3 frames and the stem bar faired.

It is submitted this trawler appears worthy to remain as classed with record of survey 8,34 without special condition.

100A1)
Stm Trawler) without etc.
8,34 Gms)



© 2021

Lloyd's Register
Foundation