

Surveyors

Received from Chief Surveyors **29 AUG 1929**

NAME

Steel Tr. Sc "TAHITI"

Report

S. 90.

No. 5853.

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Survey

Damage

When due

Subject to the indented rudder plate being dealt with at next dry docking, to indented plating &c in Dr & stables port & starboard sides forward being repaired at the first opportunity, and to indented shell plating in A stoke port side aft being dealt with at the owners convenience.



© 2021

W.F.
28.8.29

Lloyd's Register
Foundation