

Shaft renewed.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

Shaft at aft end under oil
stand being examined before
End of 7.30

17/9/24

00.2
00.20

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

