

F.E.

Received by Chief Ship Surveyor

8/12/11

Received from Chief Ship Surveyor

VESSEL'S NAME

H. L. L. Drypool

Rpt.

Kul

No.

22460

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

37.20

Depth "d"

12' 0"

Framing: Table No.

3 page 9

Description

Single angle, as approved.

Longitudinal No.

5269

Proportions

Length
Depth =

10.6

~~Deck~~ Sheerstrake

62, in line of '38 as required by Rule

RETAIN

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A-1. (Plate) Steam Trawler as recommended.

+ 100 A-1. (Plate) Steam Trawler

1/10

WB: D. Bt 23' 25"

BK 8' 4 B.H. Gen. Lloyd's 2760 274 F23

W607-0124

BEAMS, Poop Deck, Angle, Bulb Angle, Plate, }
Tee Bulb, or Channel }
Angles on upper edge

Bridge Deck Stringer Plate, br'dth & thickness

Angle on ditto.....



© 2021

Lloyd's Register
Foundation