

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 19. 12. 31 When handed in at Local Office 12 Dec 1931. Port of Hull
No. in Survey held at Hull Date, First Survey 7 Last Survey 9 Dec 1931.
eg. Book. 29542 on the Machinery of the Wood, Iron Steel S.S. K. "ROSEDALE WYKE" (EX WILLIAM DOGHERTY)
Tonnage { Gross 325 Vessel built at Selby By whom Cochrane & Sons Ltd When 1917 8
Net 132 Engines made at Middlesbrough By whom Richardson & Westgate Ltd When 1917
Nominal { 87 Boilers, when made (Main) 1917 (Donkey) ✓
orse Power } Owners West Dock Steam Fishing Co Ltd Owners' Address
No. of Main Boilers 1 Managers G. W. Robins Port Hull Voyage Fishing
No. of Donkey Boilers 1
Steam Pressure in Main Boilers 200
in Donkey Boilers ✓
A Surveyed at in Dry Dock St Andrews Slipway Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. Port
Particulars of Examination and Repairs (if any) T.S.
Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.
In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ✓
Was a damage report made by anyone else? If so, by whom? ✓
Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? no
Do. " Donkey " " " ✓
If this was not done, state for what reasons? not due for survey
And what parts of the Boilers could not be thus thoroughly examined?
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓
Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?
Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?
Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?
Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?
Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?
Was screw shaft now been drawn and examined? yes Is it fitted with continuous liner? yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? no
Was shaft now been changed? no If so, state reasons
Was the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓
State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft Rewooded
If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Tear on Slipway the Screwshaft Propeller, Stern bush and the outside fastenings of the Sea Connections examined & placed in good working order
Stern bush rewooded lower half.

General Observations, Opinion, and Recommendation:— This Machinery so far as seen is in good & efficient condition & eligible to remain as now classified, with notation of T.S.C. seen 12. 31.

Survey Fee (per Section 29) £ : : Fees applied for 19
Special Damage or Repair Fee (if any) (per Section 29.) £ : : Received by me, C. E. Miles
Travelling expenses (if chargeable) £ : : 19
Committee's Minute
Assigned As now



*It is submitted that
this vessel is eligible to
remain as CLASSED.*

*4
Km
15.12.31*

S 12.31

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation