

Undertaking

Surveyors 28 FEB 1934

Received from Chief Surveyors 2 - MAR 1934

NAME 2 Anselma de Arunaga Report Sal No. 7410

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/7/92.)

Survey 2nd No. 1 When due 2.31

MBS due 10.29 μ held
DSS due 3.30
A. due 12.31

? General Examination

The class is subject to indented plating on starboard side dealt with at the Owners' convenience.

The vessel requires to be specially examined at the next docking (grounding).

The 2nd S.S. No.1 became due 2,31 and no part of the survey was held.

The vessel being laid up the Owners have furnished the usual undertaking.

The case received consideration in February 1933 (Special Survey 2 years overdue) when a general examination was not required.

In reply to enquiry the Palmouth Surveyors now write that the vessel is still laid up.

The year of grace expired 2,32.

It is submitted for consideration whether in view of the Special Survey being now 3 years overdue the Owners should be asked to arrange for the vessel to be generally examined.

W619-0170

2020 Register Foundation

Mr Carey

Wm L. G. G.



© 2020

Lloyd's Register Foundation

1850

Wm L. G. G. Carey

1850

1850

1850

1850