

129 JUL 1930

Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

NAME Steel S.S. "PERLAK".

Rpt. Sng. No. 4722

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Survey .....

The class is subject to the rudder mainpiece, repaired by electric welding 9.28, being specially examined at the next dry docking.

The Singapore Surveyor now reports the vessel placed in dry dock, bottom coated, 1 shell plate and 2 deck plates renewed and minor repairs effected.

The rudder mainpiece, repaired by electric welding, has been examined and remains efficient and, in the Surveyor's opinion, the condition regarding same might be removed.

It is submitted the vessel appears worthy to remain as classed with record of survey 6.30, without special condition.

100 A-1. | Without etc.  
6.30 Sng  
Carrying fuel in bulk  
Fitted for oil fuel etc.



© 2021

Lloyd's Register  
Foundation

W625 0065