

of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 10982 Port Gen.

100 A.I.

W639-0017

POSTPONED SURVEYS.

Steel S.S. NORDICO".

Case of the _____
 29794
 79836 in Reg. Bk. 7261/4577 tons, Built 1903-8
 classed 100 A1 Owners *Luigi D. E. Fratelli Bozzo*
 Shells etc with food STS 6 29 NPTS 6 29 Port of Registry *Genoa*
 3-5-28 11-29 thru 3-27 181. 6.29
 Boiler Survey due 6,30.
 Survey Due _____

The Genoa Surveyors state they have been informed by the Owners that this vessel is laid up at that port and that the above survey will be carried out before she is again placed in commission.

Submitted for approval
ISA 7/8/30

Committee's Minute _____
 Decision _____

FRI. 8 AUG 1930 | FRI. 27 FEB 1931 | FRI. 24 JUL 1931
Approved | *Deferred* | *Deferred*

FRI. 12 FEB 1932 | FRI. 15 APR 1932
Deferred | *Deferred*

L Lloyd's Register Foundation

Periodical Surveys
 Shelter deck
 board 6-
 .2nd M
 .28
 BOARD (i)
 Ship an
 whom?
 rudder
 ipmer
 er Items:
 Copp
 W
 Boats
 Masts
 Condi
 (st
 Sails.
 Equip
 Ancho
 Cables
 " "
 Haws
 Stand
 vessel in t
 to remain

transfer ink
 or below the st