

25 AUG 1931

WRECK BOX

No. 72 Top

No. 12043

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 21/8/31 When handed in at Local Office 21/8/31 Port of GENOA  
 No. in Survey held at SPEZIA Date, First Survey & Last Survey 11/8/31  
 Reg. Book. 31358 on the Steel Twin Sc. "P I N C I O" (No. of Visits One)

TONNAGE:— Built at Sunderland By whom Sir J. Laing & Sons, Ltd. When 1912  
 GROSS 6092 Owners Lloyd Latino Owners' Address -  
 UNDER DECK 3578 Managers - Port belonging to Genoa  
 NET 3239

Surveyed Afloat or in Dry Dock? Afloat Name of Dock - Destined Voyage Laid up

WB=CellDBorDBa feet; uE&B feet; f feet  
 total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 16003 Port Gen

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR GENERAL EXAMINATION.-

The 2nd No. 3 Special Survey became due in June 1929, and in accordance with the Committee's requirements for a laid up vessel 12 months after the expiration of the year of grace (See London letter 26th June 1931), a general examination of the vessel was held, the particulars being as follows:—

The vessel was surveyed afloat, all holds, peaks, original side coal bunkers, now store spaces, and structure under the engines and boilers under the footplates, tween decks spaces, decks, casings, windlass, steering gear, & hatchways, being generally examined and found in order.

The oil fuel across bunkers were stated to be filled with oil and all the double bottom tanks filled with oil or water, no opportunity therefore being given for internal examination.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								
PRESENT CONDITION OF THE								
Decks <u>good</u>	State if Tanks have been examined inside <u>no</u>	Dbing. Plates under Sounding Pipes <u>✓</u>	Copper, or Y.M. of Wood Vessels <u>✓</u>					
Caulking of Decks <u>"</u>	State if Tanks now tested <u>no</u>	Engine Room Skylights <u>good</u>	(State if on Felt) <u>✓</u>					
Coamings <u>"</u>	Bulkheads <u>good</u>	Coal Bunkers, Open'gs, Lids, &c. <u>"</u>	When put on, Month <u>✓</u> Year <u>✓</u>					
Beams & Fastenings <u>"</u>	Ceiling <u>"</u>	Scuppers <u>"</u>	Boats <u>good</u>					
Outside Plating <u>"</u>	Cement or Asphalt (State which) <u>✓</u>	Cargo Hatchways <u>"</u>	Masts, Yards, &c. <u>"</u>					
Breasthooks <u>"</u>	Eudder <u>✓</u>	Hatches <u>"</u>	Condition, how ascertained <u>from deck</u>					
Transoms <u>"</u>	Steering gear and its connections <u>good</u>	Planking of Wood Vessels <u>✓</u>	(state if wedges removed) <u>no</u>					
Frames <u>"</u>	Windlass <u>"</u>	Caulking ditto <u>✓</u>	Sails <u>✓</u>					
Reverse Frames <u>"</u>	Have Pumps now been examined and found efficient? <u>no</u>	Treenails ditto <u>✓</u>	Equipment letter <u>2</u>					
Longitudinals <u>"</u>	Have Sluice Valves now been examined and found efficient? <u>✓</u>	Breasthooks & Stemson ditto <u>✓</u>	Anchors, No. of <u>5</u>					
Transverses <u>"</u>	Have Watertight Doors now been examined and found efficient? <u>no</u>	Transoms, Pointers, & Crutches ditto <u>✓</u>	Cables (State if now ranged) <u>no</u>					
Floors <u>2 peaks</u>	Have Ventilators and their Coamings been examined and found efficient? <u>no</u>	Timbers of Frame at openings ditto <u>✓</u>	„ length (on board) <u>✓</u>					
Keelsons <u>"</u>	Salting (State if examined) <u>no</u>	Ditto ditto at other places ditto <u>✓</u>	„ Rule length <u>✓</u>					
Stringers <u>"</u>		Stringers, Clamps & Shelves ditto <u>✓</u>	Hawser & Warps <u>stated sufficient</u>					
Inner Bottom Plating <u>"</u>			Standing and Running Rigging <u>good</u>					

General Observations, Opinion as to Class, Recommendation, &c.:— The vessel is eligible,

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

in my opinion, to remain as classed subject to the accepted conditions of undertaking being complied with as for vessel's laid up indefinitely.

Survey Fee (per Section 20) £ 2  
 Special Damage or Repair Fee (if any) (per Sec. 20) £ 2  
 Travelling Expenses (if chargeable) £ 10  
 Second Surveyor's Fee (if any) £ 2

Fees applied for, 21/8/31

Received by me, 19

G. A. Townsend  
 Surveyor to Lloyd's Register of Shipping.

Committee's Minute/ TUE. 1 SEP 1931  
 Character Assigned Deferred for  
20 No 3

RTAKING CASE



© 2020

Lloyd's Register  
 Foundation