

Build ... ..	Blincher	Main breadth to outside of plank ... ..	46
Galleys	None	Depth in hold from tonnage deck to ceiling at midships ...	35

C795 Pickersail 5/142 "Saint Egebert" 6/2/04

memo The Tail shafts were to L  $13\frac{3}{4}$  and are on the drawings; but owing to a slip the shafts were ordered away the same distance the fore of the cold liner, as certified on the shaft reports from Hartlepl.

ab

The shafts are  $\frac{1}{6}$  too small on the propeller rule, but still well within the 1.07 rule.

ab

Old. Rpt. 21668



© 2020

Lloyd's Register  
Foundation

W639-0260

Closed-in spaces

Space or spaces between Decks ... ..

Poop ... ..

Forecastle ... ..

Apprentices, and appropriated to their use, and kept free from goods or stores of every kind, not being the personal property of the Crew

51.444