

Steel Sc. "PARANA"

Npt. 23097

This vessel's class is subject to circulating pump being repaired.

Screw Shaft due 9.32. Approval was given by the Committee for the postponement of examination of screw shaft until the next dry docking, providing the wear down of screw shaft was not abnormal.

The Newport Surveyors now state they have examined the propeller and outside fastenings. The wear down of screw shaft is normal.

Circulating pump placed in order.

B.S. due 9.32. Partly held 12.32. Now re-held and completed.

It is submitted that the vessel is eligible for the record B.S.1.33, without special condition.

YRw

20.1.33



© 2020

Lloyd's Register
Foundation