

Chief Surveyors 26-9-34

Received from Chief Surveyors

VESSEL'S NAME

SHS FAVORITA

Report

N. YKNo. 25541**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Survey

General Examination  
(see sec 2 letter 9.8.34)

When due

He 2<sup>nd</sup> S.S. No 3 became due 6.32  
He vessel is still laid up.

No 3 starboard double bottom tank not to be used until cleared  
of further examination with cofferdam + a shell plate in D stroke  
in way of No 1 hold starboard side to be repaired at New York.  
+ repairs to be effected before vessel goes into commission

? Are the Pylons being  
used for  
see 9/6

Amend SLR



© 2021

Lloyd's Register  
Foundation

W660-8145