

W663-0057

30 MAR 1932

red by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME

Steel Sc. "TROPICO"

Rpt.

Cpn.

No. 8738

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

ure of Survey

The Copenhagen Surveyors report this vessel placed in dry dock, bottom cleaned and coated and minor repairs effected.

On account of damage, cause not stated, temporary repairs have been effected to shell plate D9 on starboard side.

The Surveyors recommend a bower anchor of proper weight and test be placed on board to replace one missing and shell plate D9 starboard side be permanently repaired at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed with record of survey 3.32, subject as recommended.

100A1) subject etc.
3.32 Cpn.)
Carrying petroleum in bulk.
Fitted for oil fuel etc.



© 2020

Lloyd's Register
Foundation