

If the Vessel has ... of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

1932 MAY 19 1932

2m.7.30.

1

Received by Chief Ship Surveyor \_\_\_\_\_ Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Shl S "GENZAN MARU" Rpt. Kof. No. 7733

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/192).

Nature of Survey \_\_\_\_\_

The Kobe Surveyors report this vessel placed in dry dock, bottom cleaned and coated and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 4.32 as recommended.

100A.1.  
4.32 Osa



© 2021 Lloyd's Register Foundation

24.5.32

Frames	---	Windlass	u	Caulking	ditto	Sails
	---	Have Pumps now been examined and found effi-		Treenails	ditto	Equipment letter