

S. S. "Ekari"

It is concluded that a set of liners for adjusting block  
and 1 bucket and rod for lubricating oil pump have  
been placed on board, but as these items are not  
listed in the list of spare gear, it is submitted the  
Glasgow Surveyors be requested to state if this is so.

W. G. L.

12/5/20

Lloyd's Register  
Foundation

W682-0369