

was a damage report made by anyone else? If so, by whom? *As Underwriters surveyors.*
Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *Yes.*

Telegrams,
"BOILER," Motherwell.
Telephone,
55 Motherwell.
Specialities,
Makers of BOILER PARTS,
FLANGED END PLATES,
CORRUGATED FURNACES,
all Sections.

JOHN MARSHALL & CO., (Motherwell) LTD.
Clyde Boiler Works,
MOTHERWELL.

21st. May 1929.

The Tyne Dock Engineering Co. Ltd.,
South Shields.

Order No.16804 of 13/5/29. S.S."SILTONHALL".

Job No:-
2821.

6 Deighton Section Corrugated Furnaces,
flanged and finished.


Plate Nos:-
2838.
2840.
2854.
2852.
2856.
2842.

Dimensions of Finished Furnaces.

Length:- 8'0"
Int. diameter:- 3'9"
Thickness:- 19/32"

Material mechanically tested by Lloyd's Surveyor
at Dalzell Steel Works, Motherwell, and found
satisfactory.

Material and Workmanship examined by Lloyd's
Surveyor at Clyde Boiler Works, Motherwell, and
found satisfactory.



© 2021

Lloyd's Register
Foundation

W685-0019