





In our opinion the machinery of this vessel is in efficient condition for the contemplated voyage.

Temporary Repairs:

Port Boiler - Centre Furnace - One additional anti-collapse ring welded to the crown of the furnace in way of the distortion.

Ballast pump overhauled and minor repairs and adjustments carried out to the main engines & pumps.

R.B.K. + W.R.

N.B.—If this Report is copied by copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register  
Foundation