

Urgent

s.s. "PETSAMO"

IT IS SUBMITTED the Copenhagen Surveyors should be informed that in the first instance it is considered that at least two plugs forward and two aft of port boiler port longitudinal seam be removed for special inspection to ascertain that there are no cracks in the shell plates and butt straps.

The result of this inspection should be cabled to this Office.

MM

Pi

Telegraph



© 12.11.31.

S.D.

Lloyd's Register
Foundation

W69-0111