

S/S "PETSAMO".

It is submitted the Copenhagen Surveyors be advised  
by cable as follows:-

"All steel plugs in double butt strapped joints of main  
boilers should be removed and butt straps and shell plates  
in way of rivet holes should be carefully examined. Sketch  
showing position of steel plaugs in main boilers to be  
forwarded to this Office."

*L.H.*  
9.11.31.

*Telahr*  
*9/11/31*



© 2020

Lloyd's Register  
Foundation

W69-0180