

S.S. "Lonsdale" Liv N^o 54806

The delay in forwarding this report was caused through the non-production of the chain and anchor certificates by the Builders, and also through some small clerical errors being found in the first report written by Mr Ashton which necessitated the re-writing of the report and again forwarding it to the Builders to be re-signed.

RM



© 2020

Lloyd's Register
Foundation

Angles on Upper Edge	442		442	
acing	234	112	234	442

" Angle on ditto	
" Tie Plates	
" Deck, Material and thickness	