

57987	150
57999	150

$\frac{1}{2}$  Len  
4  $\frac{1}{2}$

.....

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor creases and discoloration, characteristic of old paper. The right edge of the page shows the binding, with dark stitching or thread visible. There is no text or other markings on the page.

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor creases and discoloration, characteristic of old paper. The right edge of the page shows the binding, with dark stitching or thread visible. There is no text or other markings on the page.

THE UNIVERSITY OF CHICAGO PRESS

veted.

apart.  
S.

[illegible]

...

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint horizontal lines near the top and bottom edges, possibly from a previous binding or scanning artifact. A dark vertical strip is visible along the right edge, which appears to be the binding or gutter of the book. There is no text or other markings on the page.



8th. September 1919

Messrs. The Sumitomo Steel Works, Limited, Osaka.

XXXXXX

20 Nov. 1918 to 4 Feb. 1919

CAST STEEL TILLER & QUADRANT . Weight of Tiller 22 cwt 0

Magrs 6 lbs. Weight of Quadrant 36 cwt Ogrs 8 lbs.

Dropped from a height of twelve ft. on to the ground then suspended and hammered without indication of defect. Delivered in rough machined condition.

Miller				
7819-1	25.6	26		Good
Quadrant				"
71068-1	29.3	28		

AMAZON MARU

These castings are

The Osaka Iron Works, Ltd.,

Ship No. 882

60.00

7819-1  
LR  
17.1.19  
Y.J.

71068-1  
LR  
4.2.19  
Y.J.

2.00

Assist.

Y. Jo.

© 2021

Lloyd's Register  
W643-0230  
Foundation