

Box 48 Bottom

Wm. A. Register & Co. FOR LONDON

Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, or bottom plating, especially in the boiler space.

CHARACTER.	Years assigned now expired	Machinery and Boiler Surveys (including date of N.B., if any)
* for Special Survey. Date of last Survey and of Periodical Surveys.		

Society's Freeboard (if assigned) as painted on Ship and now verified } Re ins.
J. J. at 47 yrs.

Was a damage report made by anyone else? If so, by whom?

Condition

During to the bad steering qualities of the vessel a new
has been fitted further aft, and the following alterations
additions have been made:—

cut off flush with stern post, a 13"x18" keel worked under keel (12" mould forward 18" aft) and extended 20 feet - arch board perpendicular - a 13"x13" stern post fitted from deck perpendicular and fastened to and abap - cross frame at knuckle and locked 12" on to the lower keel - space

MAJOR REPAIRS:—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Faired or Repaired									
Faired in place									
ON OF THE									
Stringers		Dblg. Plates under Sounding Pipes					Copper, or I.M. of Wood Vessels		
Inner Bottom Plating		Engine Room Skylights					(State if on Belt.)		
State if Tanks have been examined inside		Coal Bunkers, Open'gs, Lids, &c.					When put on, Month Year		
State if Tanks now fitted		Scuppers					Boats		
Bulkhead		Cargo Hatchways					Masts, Yards, &c.		
Ceiling		Hatches					Condition, how ascertained		
Cement or Asphalt		Planking of Wood Vessels					(State if wedges removed)		
(State which.)		Caulking ditto					Sails		
Rudder		Treenails ditto					Equipment letter		
Steering gear and its connections		Breasthooks & Stemson ditto					Anchors, No. of		
Windlass		Transoms, Pointers, & Crutches ditto					Cables (State if now ranged)		
Have Pumps now been examined and found efficient?		Timbers of Frame at openings ditto					,, length size		
Have Sluice Valves now been examined and found efficient?		Ditto ditto at other places ditto					,, Rule length size		
Have Watertight Doors now been examined and found efficient?		Stringers, Clamps & Shells ditto					Hawser & Warps		
		Salting ditto					Standing & Running Rigging		
		(State if examined.)							

to clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon any, thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of 15," or "to remain as classed and to have record of survey, 1.15, and the notations of ss No. 1-15 and ptd15, &c."

The vessel is eligible, in my opinion, to remain
 classed and to have the fresh record 7-20 in the
 star Book

L. N. Osborn
Surveyor to Lloyd's Register of Shipping.

New York AUG 24 1923

Character Assigned

10 A1 subject

In port damaged 10.22
Not in 1934/35 R.B.

Lloyd's Register
Foundation

