

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

29 OCT. 1921

VESSEL'S NAME Steel S.S. "COMMONWEALTH"

Rpt.

Lon.

No. 84792.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

The class of this vessel is subject to the sole piece of the stern frame, repaired by electric welding in June, 1918, and again in May, 1920, being specially examined at the next dry docking.

The London Surveyors now report the vessel has been placed in dry dock, the bottom and rudder cleaned and coated.

The Electric welding at forward post of stern frame shewed a slight mark, and this has now been cut away and the part rewelded of increased area.

Three small marks on the sole piece have also been cut out and electrically welded.

It is submitted the vessel appears worthy to remain as classed with record of survey subject to the electric welding being specially examined at the next dry docking.

100A.1. 3 subeels
10.21 Lo

M.
29.10.21.

Sold for Breaking up



© 2021

Lloyd's Register
Foundation