

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 21-9-1921 When handed in at Local Office 21-9-1921 Port of Bombay

No. in Reg. Book. 25101 Survey held at Bombay Date, First Survey 21-9-1921 Last Survey 21-9-1921

Master By whom Cork, Wellington & Hemmell When 1919-2

TONNAGE:— Built at Kewerley Owners' Address A. M. Jeewanjee Port belonging to London Bombay

GROSS 197 296 Owners' Address A. M. Jeewanjee

UNDER DE. 153 249 Owners' Address A. M. Jeewanjee

NET 83 124 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Mercantile Dry Dock Destined Voyage

WB=CellDBorDBa feet; u&B feet; f feet; tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.

100 A1-8-20 L.M.C. 3.19 TS(66)

Large BATTENS NOT FITTED

Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Vessel placed in dry dock. Bottom and Rudder cleaned, examined and painted. Sound in order.

Summary of Damage Repairs:—

Plates. Frames. R. Frames. Floors. Beams. Str. Plates. Dk. Plates. Other Items:—

Renewed ...

Removed and Faired or Repaired ...

Faired or Repaired in place ...

PRESENT CONDITION OF THE

Decks ...

Caulking of Decks ...

Waterways ...

Coamings ...

Beams & Fastenings ...

Outside Plating ...

Caulking of ditto ...

Rivets ...

Breasthooks & Crutches ...

Transoms ...

Frames ...

Reverse Frames ...

Floors ...

Keelsons ...

Stringers ...

Inner Bottom Plating ...

State if Tanks have been examined inside ...

State if Tanks now tested ...

Bulkheads ...

Ceiling ...

Cement or Asphalt (State which) ...

Rudder ...

Steering gear and its connections ...

Windlass ...

Have Pumps now been examined and found efficient? ...

Have Sluice Valves now been examined and found efficient? ...

Have Watertight Doors now been examined and found efficient? ...

Salting (State if examined) ...

Dbng. Plates under Sounding Pipes ...

Engine Room Skylights ...

Coal Bunkers, Open'gs, Lids, &c. ...

Scuppers ...

Cargo Hatchways ...

Hatches ...

Planking of Wood Vessels ...

Caulking ditto ...

Treenails ditto ...

Breasthooks & Stems ditto ...

Transoms, Pointers, & Crutches ditto ...

Timbers of Frame at openings ditto ...

Ditto ditto at other places ditto ...

Stringers, Clamps & Shells ditto ...

Salting ditto ...

Copper, or Y.M. of Wood Vessels (State if on Vell.) ...

When put on, Month ...

Boats ...

Masts, Yards, &c. ...

Condition, how ascertained ...

(State if wedges removed) ...

Sails ...

Equipment letter ...

Anchors, No. of ...

Cables (State if now ranged) ...

length (on board) ...

Rule length ...

Hawser & Warps ...

Standing & Running Rigging ...

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—

survey, 1.15, or "to remain as classed and to have record of survey, 1.15, and the notations of ss No. 1-15 and ptd 15, &c."

This vessel so far as now seen is eligible in my opinion to remain as classed with fresh record of Survey 9.121.

Survey Fee (per Section 28) ...

Special Damage or Repair Fee (if any) ...

Travelling Expenses (if chargeable) ...

Second Surveyor's Fee (if any) ...

Committee's Minute ...

Character Assigned ...

TUE OCT. 25 1921

100 A1

Cargo battens not fitted

Wrecked

Lloyd's Register Foundation

W710-0265