

1
Sent to Chief Surveyors

10.4.14

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S. "Wm. Rockefeller"

Report

Phl.

No. 2588.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage

When due

Notes:

Some permanent repairs require to be effected in No. 4 oil cargo tank and 150 fms. of temporary cable, replaced by cable to rule requirements at the first convenient opportunity.
Insert as per foot of Report.

M

Wm. R.
11.4.14



© 2021

W 714-0037

Lloyd's Register
Foundation