

Do. of excess of Hatchways 32.49

Girth of Half Midship Frame (as per Rule) 52.84

By whom built *Alsia S.A.*

(2m, 9.4.)

1.

Sent to Chief Surveyors *1. 11. 04*

Received from Chief Surveyors

VESSEL'S NAME *St. S.S. "The President"* Report *Sl.* No. *22223*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey *First entry* *When due*

+ 100A1 ("Steel")

1 BK (Plt) Wall bulk.

W. B = Cell DB f 99' 1456 FPT 576 APT 106

BK 7 1/2" 38H Cem. *Plough A4CP* Q101 B10 F34 Melby Aft.

*C.H.J.*  
*1/11/04*



© 2020

Lloyd's Register Foundation

Spacing	44	-	-	44	-	-	Tie Plates	8
PILLARS, In 'tween Decks, Size and Spacing							Deck, Material and thickness	<i>Plt</i> 258
Hold	2x 34			2x 34			Forecastle Deck Stringer Plate, bndth & thcknes	23