





Screw Shaft examined and  
replaced by new one on account  
of washing at tapered part.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that  
this vessel is eligible to  
remain as CLASSED.

N.S. 9-19.

L.Y.  
27/9/19

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register  
Foundation