

Rpt. 8.

W/732

(Received at London Office)

No. 3299

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report Dec 16 1900 When handed in at Local Office

Port of Sydney N.S.W.

No. in Reg. Book.

Survey held at Sydney N.S.W.

Date, First Survey Dec 15; Last Survey Dec 15 1900

(No. of Visits)

Master W Knight

82 02 on the Wood, Iron or Steel S.S. Yongala

TONNAGE:

Built at Newcastle

By whom Armstrong Whitworth & Co. When 1900 - 10

GROSS 1664

Owners Adelaide S.S. Co. Ltd.

Port belonging to Adelaide

UNDER DECK 2902

Owners' Address

NET 1025

(If not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Woolwich

Destined Voyage Easting

WB=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B. All alterations in the existing records should be underlined. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3131 Port Syd

+100 A 1
5.530 N. 1.0 P
6.10
+5 M 6.00
B. 5.6.10

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as pointed on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Survey in dry dock

On Dec 15 the Yongala floated into Woolwich Dock where I examined the Hull, Keelson and Longship, all sound and in good condition. From keel to water line was well coated with paint and floated out early this morning.

The Cleaster did not require the services of your Surveyor

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	Good	Stringers	Not seen	Dblg. Plates under Soundings Pipes	Not seen	Copper, or Y.M. of Wood Vessels	(State if on Belt.)
Caulking of Decks	.	Inner Bottom Plating	.	Engine Room Skylights	Good	When put on, Month	Year
Waterways	.	State if Tanks have been examined inside	No	Coal Bunkers, Open'gs, Lids, &c.	Not seen	Boats	Not examined
Coamings	.	State if Tanks now tested	No	Scuppers	Good	Masts, Yards, &c.	.
Beams & Fastenings	Not examined	Bulkheads	Not seen	Cargo Hatchways	Good	Condition, how ascertained	.
Outside Plating	Good	Ceiling	.	Hatches	Not examined	(State if wedges removed)	No
Caulking of ditto	.	Cement or Asphalt (state which.)	Good	Planking of Wood Vessels	.	Sails	Not seen
Rivets	.	Rudder	Good	Caulking	ditto	Equipment letter	2
Breasthooks & Crutches	Not seen	Steering gear and its connections	Not seen	Treenails	ditto	Anchors, No. of	3 B 15 1 K
Transoms	.	Windlass	Not examined	Breasthooks & Stemson	ditto	Cables (State if now ranged)	No
Frames	.	Have Pumps now been examined and found efficient?	No	Transoms, Pointers, & Crutches ditto	.	length (on board)	120 F 140
Reverse Frames	.	Have Sluice Valves now been examined and found efficient?	No	Timbers of Frame at openings	ditto	Rule length (per Table 20)	140
Floors	.	Have Watertight Doors now been examined and found efficient?	No	Ditto ditto at other places	ditto	Hawser & Warps	Not examined
Keelsons	.			Stringers, Clamps & Shells	ditto	Standing & Running Rigging	.
				Salting	ditto		

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,09," or "to remain as classed and to have record of survey, 1,09, and the notations of ss No. 1-09 and pENDON, &c."

I recommend that the record of 12.10 be made in the Register Book in the case of this vessel

Survey Fee (per Section 20) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute

TUE. 24 JAN 1911

Character Assigned

10001



Lloyd's Register Foundation

W732-0001