

2m,7,16.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *M. V. S. Kara* Rpt. *Dws.* No. *14983*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE. *+ Docking*

Damage through *heavy weather + grounding*

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

Vessel placed in dry dock: Bottom cleaned + coated. Defective bottom rivets renewed as required and caulking dealt with. Ballast tanks examined internally and minor repairs effected.

It is submitted the vessel is worthy to remain as classed with record of Survey *12.19* as recommended.

*100A.1.
12.19 Dws.*



© 2020

Lloyd's Register
Foundation