

total capacity tons. F.P.T. tons; A.P.T. tons; M.T. tons.
N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been examined, and if so, state the amount of deterioration (if any) found in the thick plates in the boiler space.

W744-0080

Shah

Received by Chief Ship Surveyor 28.16

VESSEL'S NAME *Shah*

The remarks of the Chief Ship Surveyor are desired on this

Was a damage report

("The endorsement to contain a succinct summary of any repairs that have been required to bring out clearly any exceptional features in connection with the case, so that they may be presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey

Condition

The Bang Surveyor will examine the vessel has been examined in bottom plates & coated. The River in way of the damage engine. 1392 & two floors. The consideration of the plates has been made & found in proper on the vessel.

	Frames.	E. Frames.	Floors.
	✓	✓	✓

- Decks
- Waterways
- Coamings
- Beams & Fastenings
- Outside Plating
- Caulking of ditto
- Rivets
- Breasthooks & Crutches
- Transoms
- Frames
- Reverse Frames
- Floors
- Keelsons

- Stringers
- Inner Bottom Plating
- State if Tanks have been examined inside
- State if Tanks now tested
- Bulkheads
- Ceiling
- Cement or Asphalt (State which.)
- Rudder
- Steering gear and its connections
- Windlass
- Have Pumps now been examined and found efficient?
- Have Sluice Valves now been examined and found efficient?
- Have Watertight Doors now been examined and found efficient?

General Observations, Opinion as to Class, Recommendation

State clearly whether any and, if so, what alteration is suggested to be made in the survey, thus, for example:—"to remain as now classed in the Register survey, 1,1,1" or "to remain as classed and to have record of survey, 1,1,1, and the notation