

W75-0132

5 E

Engineer Surveyor

Received from Chief Engineer Surveyor

ME

"RESPONDO".

Rpt.

Gms.

No.

21051.

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE & WEAR AND TEAR.

Screw shaft examined; liner found cut away at middle length.

The Surveyor recommends the screw shaft be fitted with a new liner before the end of 2,40.

It is submitted the vessel is eligible to remain as classed with record of Survey S 8,39 ^{subject} / as recommended.



© 2020

Lloyd's Register
7.9.39.
Foundation