

Damage due to grounding
Screw shaft examined &
new propeller fitted.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

BS due 12. 15 now held.

It is submitted that
this vessel is eligible for
THE REG. D. BS 12. 15.

S 12. 15.

JWD
23/12/15

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation