

total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing.

CHARACTER.
* for Special Survey.
Date of last Survey and of

Years
Assigned
now
expired.

4m, 10, 13.

Wreck Box 138

1

Received by Chief Ship Surveyor 16.2.17

Received from Chief Ship Surveyor 7 FEB 1917

VESSEL'S NAME Steel S.S. "Stanley" Rpt. Nwc. No. 69610.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE. (See also Div. Rpt. no. 45538).

Damage through grounding

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	2	-		4 partly			
Removed and faired or repaired.....	20	3		3			
Faired or repaired in place.....	12	34		8			

Other items:-

Vessel examined in Dry Dock. Bottom Cleaned & Coated.
Tank Margin Plating, Tank Side Brackets & Tank Intercostals
Repaired as necessary.
Minor repairs effected.

It is submitted the vessel is worthy to remain as classed with
record of Survey 2.17 as recommended

100 A.I.

Shelter Dk. with Lbs.

2.17 Nwc.



© 2021

Lloyd's Register
757-0009
Foundation

eligible in my opinion to remain as classed