

24 FEB 1941

1

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *'RETRIEVER'* Rpt. *P. Sd.* No. *2617*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey

DAMAGE.

Damage through *Grounding (Ala. 2059)*

repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Beams	Inner Bottom Plates	Deck Plates
renewed							
removed and faired or repaired.....							
replaced or repaired in place.....							

Other items:-

*Vessel placed in dry dock
Bottom Coated*

*Some bottom plating in way of A. B and C Stakes
port and Starboard found set up and framing in
way buckled.*

Temporary repairs effected.

*The Surveyors recommend permanent repairs
to bottom plating be carried out at first opportunity.*

As submitted the vessel is worthy to remain as classed without
Order of Survey as recommended Subject as recommended

As Now. Subject etc

S.R.L. Delete dry docking (grounding)

Docking date (12.40)

