

13 NOV 1940

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

RETRIEVER

Rpt.

Alx.

No. 2059

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Nature of Survey

GROUNDING.

This vessel is reported by the *Alexandria* Surveyor

to have been examined as far as practicable afloat and by a Diver, after

Soundings taken
grounding, and so far as could be seen no damage appears to have been
but slight leakage controlled by shifts pumps found in No 1 d.c. tank
sustained, The Surveyor however recommends that *the vessel be*

*dry docked at the earliest convenient opportunity for repairs to
leaking shell rivets in way of No 1 d.c. tank*

It is submitted *action be deferred*

*Insert in S.R.L. Dry docking (grounding) and repairs
at earliest convenient opportunity*



© 2020

Lloyd's Register
Foundation

13.10.40

7010-0104