

5c, 9.14.

W. 39 T F.E.

Received by Chief Ship Surveyor 26.1.15

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. - Taipo

Rpt. Incl No. 28225

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 34.87

Depth "d" 11.42

Framing: Table No. 3 page 9

Description Single angle as approved

Longitudinal No. 4359

Proportions $\frac{\text{Length}}{\text{Depth}} = 9.8$

Deck Sheerstrake . 50 of an inch instead of .34 as reqd.

RE

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100A-1. (Steel) 'Steam Trawler', as recommended.

∇ 100A-1. (Steel) 'Steam Trawler'

1 BK
BK $7\frac{1}{2}$ 4 BK. in. Length 268' F 20'

M
26.1.15



© 2021

Lloyd's Register Foundation

W760-0063

Angles on upper edge

Tie Plates
Deck. Material and thickness