

NEW YORK

November 29, 1920.

ALEXANDER MACWATT

Owner's Representative survey the steel screw steamer "HEWITT" 5599 gross tons register of New York, for the purpose of ascertaining the nature and extent of damage stated to have been caused while docking at W. & A. Fletcher & Son Dry dock on October 22nd, 1920.

For further particulars, see log book.

On October 23rd, the undersigned upon examination found:

<u>DAMAGE</u>	<u>RECOMMENDED</u>
<u>Starboard Side</u>	
"C" Strake plate #4 indented	To be faired in place.
"D" " " #5 "	To be faired in place.
"B" & "C" plate #7 "	" " " " "
"B" & "C" strake plate #8 indented.	" " " " "
C Strake plate #9 indented.	" " " " "
"C" & "D" strake plate #10 indented.	To be cut adrift and faired in place.
<u>Port-Side</u>	
"B" Strakeplate #9 indented.	To be faired in place.
"C" Strake plates 5, 8, 9, & 10 indented.	To be faired in place.
"D" " " #11	To be faired in place.
All broken cement.	To be removed and renewed



© 2020

Lloyd's Register
Foundation

W983-0073642

S.S. "Hewitt"

-2-

DAMAGE

RECOMMENDED

where necessary.

FRE \$25.



© 2020

Lloyd's Register
Foundation

W983-0073 (2/2)