

S. S. Melania

Line 78611

It is concluded that no fuses are placed  
on the back of the switch board but the Linweya  
should confirm this as the information is  
omitted from his report.

J.F.  
9/12/24

L 12/12/24



© 2020

Lloyd's Register  
Foundation

W 80-0103