

No. of Donkey Boilers
Steam Pressure
In Main Boilers 2156

total city Boilers 10168. 1111 10168. 1111 feet: 8 1/2
Docks 6 Port 9

N.B. All alterations in the existing records should be under
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, the thicknesses of the girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 76077 Port


(Periodical surveys, when held, must be reported in detail and verbatim in the terms of the Rules on account of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs, and besides being detailed in the body of the report, should be summarised in the form shown on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether they were declined?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition:-

The vessel examined in Dry dock condition, cleaned & recoiled.

Stway



SUMMARY OF DAMAGE REPAIRS:-	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.
Renewed							
Removed and Faired or Repaired							
Faired or Repaired in place							

PRESENT CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks have been examined inside	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Steering gear and its connections	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dbing. Plates under Sounding Pipes	Engine Room Skylights	Coal Bunker & Openings, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Gaulking	Treadmills	Breasthooks & Stemson	Transoms, Pointers, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shells	Saling
Decks	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Caulking of Decks																												
Waterways																												
Collings																												
Beams & Fastenings																												
Outside Plating																												
Caulking of ditto																												
Rivets																												
Breasthooks & Crutches																												
Transoms																												
Frames																												
Reverse Frames																												
Floors																												
Keelsons																												

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notation of the vessel in the Register, thus, for example:- "to remain as now classed in the Register Book without fresh record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of No. 1-15 and PEN15, &c."

This vessel so far as seen is in good & efficient condition to remain as classed with fresh record of survey 1,15

Survey Fee (per Section 28) £
Special Damage or Repair Fee (if any) (per Sec. 29) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Received by me, £
10

Committee's Minute
Character Assigned

LIVERPOOL

100 A1



Surveyor to Lloyd's Register

Lloyd's Register Foundation