

W82-023

Surveyors: 30/12/12  
NAME: At Motor Barge Silver Queen Report No. 68753

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

On cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/12

Survey: Just entry When due

± A-1. (Old) Motor barge for River purposes only  
Subject to the Windlass cable holder being adjusted  
1 Dr (Dtt) + Web frames. Longitudinal framing  
FR. 2B & Open partition bulkhead between engine  
space & cargo hold, Bern. Lloyds & C.P.

M. Z.B.N.  
31/12/12

© 2019  
Lloyd's Register  
Foundation

	23	30	✓	Deck Stringer Plate, br'dth & thickness
Angles on upper edge	✓	✓	✓	Angles on ditto, No.
Ray of Long Bridge	✓	✓	✓	Tie Plates, outside Hatchways
	✓	✓	✓	Deck * Material and thickness