

rails, ribs, windlass, pumps, m.t. doors
firing examined, overhauled in good
This vessel was examined by the
the technical staff of the yard and the
Engineer of the Navy superintending the
because owing to the change of name
vessel the Surveyor did not know that
was classed

Repairs now carried out:

Divisional bulkheads in bulkheads re

Wood ceiling on starboard bulkhead re

Steel deck of port bulkhead repaired

One plate in tween deck renewed

M.T. bulkhead between bulkhead and

in tween deck repaired

Sounding pipes in hold No. 2 renewed

the ink, or to cause it to show through to the other side.

Lloyd's

INSTRUCTION

The Surveyor
No. 10), a
recked, cond
curring in t
n.

The qua
e returns w
the nature
egards each ca

The Surv
ticular attention is
vessels, and he
reported in sl
ape early at
ported to the
ates of disman

FRID 3 JAN 1920

Referred

Wm. G. G. G. G. G.

"

Li



© 2020

Lloyd's Register
Foundation