

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 26-5-17

Port of MANCHESTER

No. in
Reg. Book.

Survey held at

PARKINGTON

Date, First Survey

26-5-17

Last Survey

26-5-

1917

on the Wood, Iron or Steel

SS. "LUDGATE"

(No. of Visits

one

Master

J. H. Merriam

When 1906

MONTH

TONNAGE:-

Built at

Sunderland

By whom

Barham Bros.

GROSS 3708

Owners

Carrington SS Co. Ltd (Williams & Morley, Mgrs.)

Port belonging to

London

UNDER DEK 3484

Owners' Address

NET 2390

(if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock? Afloat

Name of Dock

Parkington Coal Dips

Destined Voyage

Govt. Service

WB=CellDBorDBa

feet; uE&B

feet; f

feet; l

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3678

Port

Dub

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.

Date of last Survey and of Periodical Surveys

Year

Assigned

now

expired.

Machinery and Boiler

Surveys

(including date of N.B., if any).

+100A1.

+LMC.

1-17.

MS 5-14.

SS. Son. No. 2-14.

BS 5-16.

TS 1-17.

Society's Freeboard (if assigned) as painted on Ship and now verified

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Testing After Pk. Tank.

See Barry Rept. No. 15917.

d. Gib. Rept. No. 840.

After Peak tank tested by head of water and found to be slightly leaking on the Port side in way of Hold Stringer face gasket Connection lug.

As the vessel was taking in a cargo of coal nothing could be done at this time. The above mentioned leak. The Sup^t stated that this will be attended to at the first available opportunity. The vessel's efficiency is not affected, and it is not intended to carry water ballast in the After Pk. Tank while the vessel is carrying cargo.

In my opinion repairs might be deferred as proposed.

Marconi wireless installation fitted on board.

DAMAGE REPAIRS:-

Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

and Faired or Repaired

Repaired in place

CONDITION OF THE

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested. After Pk. Tank.

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Dblg. Plates under Sounding Pipes.

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels.

Caulking

Treenails

Breasthooks & Stems

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shells ditto

Salting

(State if examined.)

Copper, or Y.M. of Wood Vessels.

(State if on Felt.)

When put on, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

length size

(on board)

Rule length size

Hawser & Warps

Standing & Running Rigging

Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon the survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Survey, 1,15, and the notations of ss No. 1-15 and ptnD15, &c."

Vessel so far as now seen is eligible in my opinion to remain as classed without record of Survey, subject to the After Pk. Bulkhead being made tight and retested at the available opportunity. Record of Wireless to be noted.

Section 22)

Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Committee's Minute

Character Assigned

Fees applied for,

19

Received by me,

19

Robt. Cheetham

Surveyor to Lloyd's Register of Shipping.

FRI 8 JUN 1917

Subject BS 5.17

W831-0135

Lloyd's Register Foundation