

50,914.

F.E.

Received by Chief Ship Surveyor 21. 10. 15

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. S. S. "Maplewood" Rpt. Mdb No. 9105

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 72. 63Depth "d" 21. 66Framing: Table No. 3 page 15 Description Bulb angleLongitudinal No. 24331Proportions $\frac{\text{Length}}{\text{Depth}} =$ 10. 2Bridge Deck Sheerstrake as approved.

The anchor were approved subject to the Owners consent & this has been obtained.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to


be classed 1- 100 A.1. (Steel) as recommended.

1- 100 A.1. (Steel)

1 LK (p¹ Sm & p¹ SH.)

WB. Hull DBA, 110' 4" E 22', f 145', 812 t, APT 86t,

FK, 5 BH, Cmw. Lops A 6 P. P 31, B 100, F 35.



© 2020

Lloyd's Register Foundation

W835-0005