

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 14.5.14 When landed in at Local Office 14.5.14 Port of GRIMSBY

No. in Reg. Book. 353 on the Wood, Iron or Steel S.K. "MANX HERO" Date, First Survey 6 May 1914 Last Survey 12 May 1914

TONNAGE:— Built at Selby By whom Bochrane & Sons When 1910.9

GROSS 221 UNDER DE 197 Owners' Address W. H. Bealey Port belonging to Grimsby

NET 102 Owners' Address (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Both Name of Dock Fish. Destined Voyage Fishing

WB=CellDBorDBa feet; uE&B feet; f feet; l capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

st Report, No. 9201 Port Gms.

Medical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR special Survey &c.

Done:— Vessel placed in dry dock; Bottom cleaned, examined, and recoated.

Holds, peaks, bunkers & machinery space cleared, ceiling lifted as required by the Rules, accommodation & fish room lining partly removed.

and all ironwork where exposed, examined and found in order. Cement

bottom, decks, masts, steering gear, windlass, pumps, w.t. doors, hatches

air cables, and general equipment examined, and found or put in

good order.

On starboard side, in way of side bunker, one main structural plate

removed, failed replaced.

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptd11, &c."

This vessel is eligible in my opinion to remain as classed, and to have fresh record of Survey 5.14, and notation 7.55 Gms 1-14

Survey Fee (per Section 20) £ 2

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for, 4.5.14

Received by me, 26/6/14

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute

Character Assigned 100A1 Steam Trawler

5.5 Gms. 1-14

7.55 Gms 1-14

W837 0041

© 2021 Lloyd's Register Foundation